



PH Meter



- ✓ Direct display of hardness scales HRB, HRC, HV, HB, HS and HL
- ✓ Conversion to tensile strength
- ✓ Test any angle
- ✓ Wide measuring range

| Model | PH METER |
|---------------|---|
| Test Range | PH: 0 ~ 14 ph ± 0.03ph mV: 0 ~ 2000mV ± 0.5% temperature: 0 ~ 100°C ± 0.8°C |
| Display | LCD Display maximum & minimum range |
| Dimension | 180 x 72 x 32 mm (WxDxH) |
| Port | RS-232 |
| PH electrodes | PE-03, PE-11, PE-04HD, PE-06HD, PE-01, PE-03K7 (optional) |